



NOTES:

1. REMOVE ALL LEAD AND OTHER FLASHING BEFORE INSTALLING FIELD FABRICATED PIPE SEAL.
2. QUICK APPLIED UNCURED EPDM FLASHING WRAPPED AROUND THE PIPE SHALL HAVE 3" (75 mm) MINIMUM MEMBRANE SPLICE.
3. TEMPERATURE OF METAL COLLAR MUST NOT EXCEED 180° F (82° C).
4. IN COLDER TEMPERATURES, A HEAT GUN MUST BE USED WHEN FORMING GA UNCURED EPDM FLASHING.

C-14.2

FIELD FABRICATED NEW HOT STACK