



NOTES:

1. USE A HEAT GUN TO WARM QA UNCURED EPDM FLASHING IN COLD TEMPERATURES.

C-15.4 (OPTION 2)
OUTSIDE CORNER/QA UNCURED EPDM FLASHING

VERSICO
INCORPORATED



A subsidiary of Carlisle SynTec Incorporated
© 2006 VERSICO INCORPORATED