

PVC OUTSIDE CORNERS

GENERAL:

PVC Outside Corners are pre-molded and are used for flashing outside corners. Installation is fast and easy with no cutting or stretching required. This product is white on gray and can be reversed to use on a gray PVC installation.

TYPICAL PROPERTIES AND CHARACTERISTICS:

Thickness:	.080" (2.03 mm)
Color:	White and Gray

CAUTIONS AND WARNINGS:

1. Store pre-molded corners in a cool, shaded area and cover with light-colored, breathable, waterproof tarpaulins. PVC Outside Corners or PVC membrane that has been exposed to the weather must be prepared with PVC Membrane Cleaner prior to hot air welding.

INSTALLATION:

1. Begin welding at the innermost corner point and work away from the corner.
2. Use a lower temperature setting on the heat welder than when welding the reinforced membrane. Typically a setting of "6" on a scale of "10" is appropriate for welding PVC Outside Corners.
3. Use the edge of the roller to crease the corner flashing into any membrane step-off for a proper seal.